AdjusterOnline™
adjusteronline.net | info@adjusteronline.net

PRELIMINARY REPAIR ESTIMATE

No. |

Customer		**Vehicle**	2019 Freightliner Cascadia sleeper tractor
Phone / Email		**VIN**	
Date of loss	-	**Color**	Red
Request #		**Mileage**	620000 (NOT ACTUAL - from last record)

Repair operations

#	Operation	Description	Part / basis	Part $	Body h	Paint h	Mech/Fr h	Labor $
Hood								
1	Replace	Hood assembly with integrated fenders, new (parts only). LH side is torn at the headlamp opening and wheel arch.	OEM hood assembly allowance, verify by VIN	$6,000.00				
2	Remove	Remove damaged hood assembly: disconnect harness, release tilt dampers and pivots, lift off	Labor only		2.4			$360.00
3	R&I	Transfer grille assembly with emblem from old hood to new hood	Existing		1.0			$150.00
4	R&I	Transfer RH headlamp from old hood to new hood	Existing		0.6			$90.00
5	R&I	Transfer RH hood-mounted mirror to new hood	Existing		0.6			$90.00
6	R&I	Transfer LH and RH hood side air-intake vent grilles	Existing		0.8			$120.00
7	R&I	Transfer LH and RH Cascadia badges	Existing		0.4			$60.00
8	R&I	Transfer hood wiring harness and connectors to new hood, route and secure, function test lamps	Existing				M 1.8	$270.00
9	Prep	Prep new hood: scuff, clean, apply sealer/primer to new composite panel	Labor only			3.0		$450.00
10	Refinish	Refinish exterior of new hood (base/clear, body color)	Labor only			7.2		$1,080.00
11	Refinish	Refinish edges and visible inner flanges of new hood	Labor only			1.8		$270.00
12	Install	Install new hood on pivots, connect tilt dampers and harness	Labor only		2.4			$360.00
13	Align	Align and adjust hood gaps to cab, bumper and doors; adjust hood latches	Labor only		1.2			$180.00
Left Headlamp								
14	Replace	LH headlamp assembly, crushed (parts only)	OEM headlamp allowance, verify by VIN (halogen vs LED)	$1,100.00				
15	Install	Install new LH headlamp in new hood and connect	Labor only		0.6			$90.00
16	Align	Aim LH and RH headlamps	Labor only				M 0.6	$90.00
Front Bumper LH End								
17	Repair	Repair scrapes and gouges on LH bumper end section	Existing		1.8			$270.00
18	Refinish	Refinish LH bumper end section	Labor only			2.4		$360.00

AdjusterOnline Estimate

#	Operation	Description	Part / basis	Part $	Body h	Paint h	Mech/Fr h	Labor $
19	Blend	Blend adjacent painted center bumper section for color match	Labor only			1.2		$180.00
Left Driver Door								
20	Repair	Repair dent on driver door outer panel (customer-reported; priced as a medium dent pending close-up)	Existing		3.6			$540.00
21	Refinish	Refinish driver door exterior	Labor only			3.0		$450.00
22	Blend	Blend adjacent LH cab/sleeper side panel behind door for color match	Labor only			1.8		$270.00
Left Driver Door Glass								
23	Replace	Driver door glass (customer-reported broken; window opening shows no glass in photos)	OEM door glass allowance, verify by VIN	$350.00				
24	Install	Remove door trim panel, remove glass remnants and debris from door and cab, install new glass, reinstall trim	Labor only		1.8			$270.00
Left Driver Door Mirror								
25	Replace	Driver door mirror assembly (customer-reported damaged)	OEM mirror assembly allowance, verify by VIN (heated/power)	$900.00				
26	R&R	Remove damaged mirror, install new mirror, connect and adjust	Labor only		1.0			$150.00
Right Chassis Fairing								
27	Replace	RH front chassis fairing section, missing (parts only)	OEM fairing allowance, verify by VIN	$1,100.00				
28	Install	Install RH front chassis fairing section	Labor only		1.2			$180.00
29	Refinish	Refinish new RH front chassis fairing section (body color)	Labor only			1.8		$270.00
30	Replace	RH center chassis fairing section, missing (parts only)	OEM fairing allowance, verify by VIN	$1,300.00				
31	Install	Install RH center chassis fairing section	Labor only		1.2			$180.00
32	Refinish	Refinish new RH center chassis fairing section	Labor only			1.8		$270.00
33	Replace	RH rear chassis fairing section, missing (parts only)	OEM fairing allowance, verify by VIN	$900.00				
34	Install	Install RH rear chassis fairing section	Labor only		1.2			$180.00
35	Refinish	Refinish new RH rear chassis fairing section	Labor only			1.5		$225.00
Right Chassis Fairing Mounts								
36	Replace	RH chassis fairing mounting brackets (customer-reported missing; allowance for one side set)	OEM bracket allowance, verify by VIN	$450.00				
37	Install	Install RH chassis fairing mounting brackets to frame/tank supports	Labor only		1.8			$270.00

AdjusterOnline Estimate

#	Operation	Description	Part / basis	Part $	Body h	Paint h	Mech/Fr h	Labor $
Right Steps								
38	Replace	RH internal step carrier frame, missing (parts only)	OEM step carrier allowance, verify by VIN	$650.00				
39	Install	Install RH step carrier frame	Labor only		1.8			$270.00
40	Replace	RH upper step tread, missing (parts only)	OEM step allowance, verify by VIN	$250.00				
41	Install	Install RH upper step tread	Labor only		0.6			$90.00
42	Replace	RH lower step tread, missing (parts only)	OEM step allowance, verify by VIN	$250.00				
43	Install	Install RH lower step tread	Labor only		0.6			$90.00
Sleeper Rear Extenders								
44	Replace	Upper LH sleeper side extender panel, missing (bracket arms visible, panel absent)	OEM extender allowance, verify by VIN	$850.00				
45	Install	Install upper LH sleeper side extender panel	Labor only		0.8			$120.00
46	Refinish	Refinish new upper LH extender panel	Labor only			1.2		$180.00
47	Replace	Lower LH sleeper side extender panel, missing	OEM extender allowance, verify by VIN	$650.00				
48	Install	Install lower LH sleeper side extender panel	Labor only		0.8			$120.00
49	Refinish	Refinish new lower LH extender panel	Labor only			1.2		$180.00
50	Replace	Upper RH sleeper side extender panel, missing	OEM extender allowance, verify by VIN	$850.00				
51	Install	Install upper RH sleeper side extender panel	Labor only		0.8			$120.00
52	Refinish	Refinish new upper RH extender panel	Labor only			1.2		$180.00
53	Replace	Lower RH sleeper side extender panel, missing	OEM extender allowance, verify by VIN	$650.00				
54	Install	Install lower RH sleeper side extender panel	Labor only		0.8			$120.00
55	Refinish	Refinish new lower RH extender panel	Labor only			1.2		$180.00
Sleeper LH Cab Attachment								
56	Repair	Repair torn LH rear cab extender attachment area (customer-reported; assumed localized composite repair, not panel replacement)	Existing		2.4			$360.00
57	Refinish	Refinish repaired LH cab attachment area	Labor only			1.2		$180.00
Sleeper RH Cab Attachment								
58	Repair	Repair torn RH rear cab extender attachment area (customer-reported; assumed localized composite repair, not panel replacement)	Existing		2.4			$360.00
59	Refinish	Refinish repaired RH cab attachment area	Labor only			1.2		$180.00

R&I = remove and install. R&R = remove and replace. INC = labor covered by another operation. M = mechanical. F = frame.

Totals

Parts	$16,250.00
Body labor 34.6 h x $150	$5,190.00
Refinish labor 32.7 h x $150	$4,905.00
Mechanical 2.4 h x $150	$360.00
Hood paint materials: 12.0 refinish hrs x $50/hr (estimated rate)	$600.00
LH bumper end paint materials: 3.6 refinish hrs x $50/hr (estimated rate)	$180.00
Driver door and blend paint materials: 4.8 refinish hrs x $50/hr (estimated rate)	$240.00
RH chassis fairings paint materials: 5.1 refinish hrs x $50/hr (estimated rate)	$255.00
Sleeper extenders paint materials: 4.8 refinish hrs x $50/hr (estimated rate)	$240.00
LH/RH cab attachment areas paint materials: 2.4 refinish hrs x $50/hr (estimated rate)	$120.00
Body materials (composite repair resin, filler, adhesive, clips): approx. 34.6 body hrs x $6/hr	$210.00
Extender and fairing fasteners/hardware kit (estimated)	$210.00
Post-repair electrical/diagnostic scan (estimated)	$250.00
Hazardous waste disposal	$5.00
Sales tax est. 6% on parts & materials	$975.00
ESTIMATE TOTAL	**$29,990.00**

Items pending inspection or confirmation (not in total)

- Behind LH hood corner: headlamp mounting brackets, hood pivot/tilt damper, LH bumper end bracket, radiator/charge-air cooler LH edge and hood harness need inspection after hood removal (covered by the worst-case amount, not priced in
- LH (driver) hood-mounted mirror does not appear in the photos at its usual location; needs to be checked to confirm whether it is missing or damaged. Not priced.
- LH (driver side) center and rear chassis fairings are not visible in the photos; condition unknown, not priced.
- Rear sleeper extender bracket arms (upper/lower, LH/RH) appear present in the photos; bracket condition and hinge hardware to be inspected. Bracket replacement not priced.
- Batteries reported stolen: batteries, cables and battery box are not included in this repair estimate. The electrical scan and lamp function tests require batteries to be installed.
- Driver door glass and door dent are priced as customer-reported; the photos do not clearly show broken glass (a lowered window looks the same) or the dent.

Additional photos that would improve accuracy

- VIN plate/label close-up (driver door jamb)
- Close-up of driver door from 45 degrees showing the dent, plus driver door window opening and inner door glass area
- Close-up of driver door mirror (front and back)
- LH front hood corner where the driver hood mirror mounts
- Close-ups of each rear sleeper corner (upper LH, lower LH, upper RH, lower RH) showing brackets and torn attachment points
- Passenger side under door: step carrier location and fairing mounting points
- Driver side full length from front wheel to rear axle (center/rear fairings)
- Behind LH headlamp opening with hood tilted (brackets, cooling module, harness)

Price sources

- OEM list price allowances, estimated; verify by VIN with a Freightliner dealer

- Typical labor times, estimated by appraiser for a 2019 Cascadia sleeper (no labor guide supplied)
- Paint materials estimated at $50 per refinish hour
- Customer photos (4) and customer damage description

This is a preliminary estimate prepared from photos provided by the customer. Hidden damage found after disassembly may change the final cost. Labor times are approximate. Sales tax is an estimate. This estimate is not a guarantee of repair cost or of insurance payment. Rates used: body/refinish 150/h, frame 150/h, mechanical 150/h. Paint & materials are estimated separately in the totals when applicable.

Photos submitted with this request

Photo 1 of 4 - Damage photo 1



Photo 2 of 4 - Damage photo 2



Photo 3 of 4 - Damage photo 3



Photo 4 of 4 - Damage photo 4

