Your repair estimate at a glance

2019 Mercedes-AMG C43 Cabriolet

What was damaged

Rear-end collision damage. The estimate covers the rear bumper, trunk lid, rear lighting and related repair operations described on the following pages.

Preliminary repair estimate

$12,028.80

If the listed hidden damage is confirmed

$17,828.80

This is one possible scenario after disassembly. A physical inspection is needed to confirm the hidden damage and the final repair cost.

What to do next

Share the itemized estimate with your repair shop. Ask the shop to confirm the scope, inspect for hidden damage and review the final cost before repairs begin.

AdjusterOnline™
adjusteronline.net | info@adjusteronline.net

PRELIMINARY REPAIR ESTIMATE

No. SAMPLE-VOR5 | 11/13/2026

Customer	Sample customer	**Vehicle**	2019 Mercedes-Benz C-Class AMG C43 4MATIC Cabriolet
Phone / Email	Withheld for privacy	**VIN**	Withheld for privacy
Date of loss	2026-11-04	**Color**	Dark gray metallic (paint code to be confirmed from door-jamb label)
Request #	SAMPLE-VOR5	**Mileage**	48000 (Actual)

Damage lines

#	Area	Op.	Description	Part $	Body h	Paint h	Mech/Fr h
1	Rear bumper	Replace	Rear bumper cover, AMG C43 Cabriolet, primed (OEM A205 885 series, est.)	$1,250.00	3.6	3.6	
2	Rear bumper	Replace	Rear bumper lower diffuser insert, AMG (OEM est.)	$780.00	0.6		
3	Rear bumper	Replace	Rear bumper reinforcement bar (OEM est.)	$520.00	1.2		
4	Rear bumper	Replace	Rear impact absorbers / crash boxes L & R (OEM est.)	$380.00	1.0		
5	Rear bumper	Replace	Rear bumper cover guide brackets L & R and center mounts (OEM est.)	$160.00	0.5		
6	Rear bumper	Replace	Rear parking sensors, center (2), with brackets (OEM est.)	$340.00	0.5		
7	Rear bumper	R&I	Blind-spot radar sensors L & R, remove and install with bumper				0.6
8	Rear bumper	Replace	License plate bracket (OEM est.)	$60.00	0.2		
9	Trunk lid	Replace	Trunk lid, Cabriolet (OEM est.), incl. transfer of hardware	$1,650.00	3.0	4.2	
10	Trunk lid	R&I	Trunk lid spoiler, AMG, remove/install and refinish		0.5	1.4	
11	Trunk lid	Replace	Trunk lid emblems (star and AMG C43 badge), one-time adhesive (OEM est.)	$110.00	0.3		
12	Trunk lid	Replace	RH inner tail lamp (trunk lid mounted), LED (OEM est.)	$520.00	0.4		
13	Trunk lid	R&I	LH inner tail lamp (trunk lid mounted)		0.3		
14	Trunk lid	R&I	Trunk handle / rear camera / license lamp unit		0.6		
15	Trunk	Replace	Trunk lid weatherstrip (OEM est.)	$120.00	0.4		
16	Rear body	Replace	Rear body panel (rear end panel), welded (OEM est.)	$640.00	10.8	3.0	
17	Rear body	R&I	Outer tail lamps L & R (quarter mounted) for panel access		0.6		
18	Trunk interior	R&I	Trunk trim panels, rear sill trim and floor covering		1.2		
19	Exhaust	R&I	Rear exhaust mufflers/tips for rear panel welding access				1.2
20	RH quarter panel	Blend	Blend RH quarter panel for color match			1.8	
21	LH quarter panel	Blend	Blend LH quarter panel for color match			1.8	
22	Structure	Repair	Frame bench set-up and 3D measure of rear structure				3.0 F

Totals

Parts	$6,530.00
Body labor 25.7 h x $68	$1,747.60
Refinish labor 15.8 h x $68	$1,074.40
Paint & materials 15.8 h x $50	$790.00
Frame / structural 3.0 h x $93	$279.00
Mechanical 1.8 h x $127	$228.60
Pre-repair diagnostic scan	$95.00
Post-repair diagnostic scan	$95.00
Blind-spot radar calibration (rear)	$350.00
Rear camera calibration / verification	$250.00

SAMPLE

Corrosion protection, weld-through primer, seam sealer	$85.00
Body materials and supplies (clips, fasteners, adhesives)	$60.00
Hazardous waste disposal	$5.00
Sales tax est. 6% on parts & materials	$439.20
ESTIMATE TOTAL	**$12,028.80**

Estimate range: $12,028.80 - $17,828.80 (visible + likely damage -> worst case after teardown).

Possible hidden damage (not included in total)

- Rear rail ends / rear frame rail tips may be pushed - sectioning or pull possible after measuring
- Trunk floor and spare/battery well buckling
- Rear exhaust mufflers and AMG tips, hangers
- Remaining rear parking sensors and wiring harness in bumper
- Trunk lock/latch, striker and power trunk closing components
- Convertible top storage compartment partition, top compartment lid and top linkage near trunk opening
- RH quarter panel at bumper/tail lamp joint and quarter lower extension
- Trunk lid hinges and gas struts / hinge mounting area
- Worst case after teardown (rear rails, trunk floor section, exhaust, top compartment parts): approx. $5,800 additional

Additional photos that would improve accuracy

- Straight-on rear view from about 6 feet, full bumper and trunk lid
- Close-up of RH rear corner: bumper, quarter panel joint and outer tail lamp
- Close-up of LH rear corner: bumper and quarter panel joint
- Trunk opened: rear body panel inside, trunk floor, spare/battery well, top compartment
- Underneath the rear: exhaust tips, mufflers and rear frame rail ends
- Paint code label (driver door jamb)
- Dashboard with ignition on showing any warning messages

Price sources

- Mercedes-Benz OEM parts list prices (dealer catalog estimates, 2026)
- Industry-standard collision labor times (CCC/Mitchell level)
- Customer photos: odometer, VIN plate, two rear-quarter damage views

This is a preliminary estimate prepared from photos provided by the customer. Hidden damage found after disassembly may change the final cost. Labor times are approximate. Sales tax is an estimate. This estimate is not a guarantee of repair cost or of insurance payment. Rates used: body/refinish $68/h, frame $93/h, mechanical $127/h, paint & materials $50 per refinish hour.

SAMPLE